continue to pump water on site		Date:				U.	S. EPA	Region
VORK AUTHORIZED:		Date: 5-26-2015  Division/ Group: Response			DAILY WORK ORDE Emergency and Rapid Response Service			
VORK AUTHORIZED: continue to pump water on site								
		•						
Continue development of profile				,				
Oita Oanalias II		, and waste, from the ASTs, Frac Tanks, Totes, and Drums.  On-Scene Coordinator: ERRS Response Manager						
170 008950461								
		Gary Moore, USEPA			LeRoy Cassidey, CB&I Federal			
Task Order: 062		Date: 5.26	.2015	Time:1700	Date: 5	5.26.2015	Time: 170	00
ERSONNEL ON-SITE:	QTY	Used	Unused	EQUIPMENT ON- SITE:		QTY	USED	Unused
Response Manager	1	0		Pick –up Tr	uck	2	1	
Foreman	1	1		Genera	ator	1	0	
Equipment Operator	0	0		Trash Pur	nps	0	0	
Truck Driver	1	0		Utility Tra	ailer	0	0	
Laborer	2	0		Frac Tank w L	iner	1	0	
Health and Safety Manager	0	0		4,000 PSI Press Was		1	0	
PERSONNEL OFF-SITE				Open Top Roll	Off	5	0	
Subcontract Manager	1	1		Vacuum Truck Air Mover		1	0	
Fransport and Disposal Coord	1	1		Carbon Vapor I	Unit	0	0	
Field Cost Accountant	1	1		Skid St	teer	0	0	
				Vacuum/OT Bo	xes	9	0	
				9,000 lb Overhead	Lift	1	0	
				Storage Tra	ailer	1	0	
				Myers (Bean) Pu	ımp	1	0	
				Air Compres	ssor	1	0	
				Rental	Car	1	0	

Next OPERATIONAL PERIOD (administrative, tactical / status changes, special instructions, H&S)(Input for next DWO):

Clean up, cut up vacuum hose place in US Ecology roll off. Cut up dirty totes place in same box. Place PPE in some box. Clean up lime spill area. Remove liquids fom Warehouse Bay Trenches. Pump water as needed.